

Volume 2, Issue 9

September 2011



**Project Spotlight:
'Holy Family Catholic Church'**

Address: Dale City, VA
Areas Completed: 5,342 sqft.
Services: Dye Stain & Seal
Project Challenges: N/A



Tip Corner

- Stained Concrete vs. Other Flooring Materials-

	Wall-to-wall carpet	Ceramic tile	Vinyl or linoleum	Wood or wood laminate	Decorative Concrete
Available in a wide spectrum of colors	Yes	Yes	Yes	No	Unlimited
Longevity & performance	Poor	Good	Good	Good	Excellent
Handcrafted & customizable	No	No	No	No	Yes
Humidity & moisture damage	Yes	No	Yes	Yes	No
Can harbor mold, mildew, dust mites and other allergens	Yes	No	No	Yes (mold and mildew, if the flooring becomes wet)	No
Average cost per square foot installed	\$3.38 - 6.61	\$11 - 22	\$2.64 - 5.64	\$8 - 10	\$2 - 15+

GO FROM GRAY... TO GORGEOUS
BSI Newsletter

"Service = The sum of many little things done well"